

**SUBJECT:**           **Retrofitting R-12 Air Conditioning with R-134a**

**MODEL:**           E23 / E24 / E28 / E30

**Situation:**       Retrofit kits are available for the above models for customers who wish to convert their R-12 A/C system to the newer, more environmentally-friendly R-134a refrigerant.

**Solution:**        A retrofit kit may be installed as a "customer-pay" accessory. Although so far this procedure is not a necessary part of any general A/C repair, we highly recommend encouraging the customer to consider this environmentally-friendly solution. This is particularly the case if the compressor needs replacement; we recommend the retrofit be performed at that time. For the customer, there is only a minimum additional cost for retrofitting his A/C system, compared to the costs of only replacing the compressor.

**Some models are equipped with BOSCH A/C compressors, which are not compatible with R-134a refrigerant. Those compressors must be replaced when the system is being converted to R-134a.**

The following list shows the models with factory-installed compressors which are **NOT R-134a compatible** :

| <b>Body</b> | <b>Model</b>      | <b>Production Date</b> |
|-------------|-------------------|------------------------|
| E23         | 735i              | All                    |
|             | L7                | All                    |
| E24         | 635CSi            | All                    |
|             | M6                | All                    |
|             | Rear A/C units    | All                    |
| E28         | 528e              | 7/85 - 3/87            |
|             | 535i              | 7/85 - 12/87           |
|             | M5                | 9/87 - 11/87           |
| E30         | 318i              | 7/85 - 8/85            |
|             | 325e, 325i, 325iC | 7/87 - 10/88           |
|             | 325iX, M3         | All                    |

The above list should not be the only deciding factor, since a non-R-134a compatible compressor might have been installed on a previous A/C repair on these, or other, models.

A non-compatible BOSCH compressor may be identified by its part number. Please refer to the following list of non-compatible BOSCH compressors:

| <b>A/C compressor, part number</b> | <b>Adapter wire required?</b> |
|------------------------------------|-------------------------------|
| 64 52 1 377 940                    | yes                           |
| 64 52 1 377 941                    | yes                           |
| 64 52 1 377 943                    | yes                           |
| 64 52 1 377 944                    | no                            |
| 64 52 1 377 946                    | yes                           |
| 64 52 1 377 947                    | no                            |
| 64 52 1 385 416                    | no                            |
| 64 52 1 385 930                    | no                            |
| 64 52 1 386 411                    | no                            |

If a vehicle is equipped with one of the compressors listed above, the compressor must be replaced by the compressor **P/N 64 52 8 363 550** , when the system is being converted to R-134a. For some of the compressors (specified in the above list), an additional adapter wire for the magnetic clutch **P/N 64 52 1 386 224** is required.

**Compressor and adapter cable are not part of the retrofit kit. They must be ordered separately if required.**

**Procedure:**

The following procedure replaces the steps listed in the installation instructions included with the kit. The information has been revised and expanded for clarity:

1. Safety Precautions when Handling Refrigerant

A/C systems are filled with refrigerant under pressure. Safety precautions must be followed when working with these systems. Refer to [S.I. 64 10 92 \(3536\)](#) for a list of procedures relating to safe refrigerant handling.

2. Evacuating and Removing Mineral Oil from the A/C System

2.1 Evacuate the A/C system using an approved R-12 recovery/recycling machine. Follow the directions included in the machine's instruction manual.

2.2 If you are replacing the compressor, follow this step; otherwise, skip to 2.3.

Replace the compressor according to the appropriate repair manual. Install the adapter wire for the magnetic clutch, if necessary.

2.3 Recharge the A/C system with R-12. Fill with the quantity of R-12 specified on the vehicle A/C label, or refer to S.I. 64 01 90 (3042). **Do NOT add any oil when recharging with R-12.**

2.4 Start the engine and turn on the A/C system. Run the vehicle with the A/C system turned on, engine at idle, for 10 minutes.

2.5 Repeat steps 2.1 through 2.4. This will remove most of the mineral oil from the R-12 system during the discharge. The remainder of the oil will be collected in the bottom of the receiver-dryer, which will be replaced. Any residual mineral oil left in the system will remain in the evaporator or condenser, and is not harmful to the retrofitted system.

2.6 Evacuate the A/C system.

### 3. Converting the A/C System Components

#### 3.1 NOTE

##### **E30 models only**

Apply the new pressure switch onto the new receiver dryer, using a new O-ring. All components are provided with the retrofit kit.

##### **All models except E30**

Remove the pressure switch/switches from the old receiver dryer and install it/them into the new receiver dryer, using new O-rings. All components are provided with the retrofit kit.

3.2 Replace the old receiver dryer with the new unit along with the pressure switch/switches. Replace the O-rings on all receiver dryer connections opened during the retrofit procedure. All necessary O-rings are provided in the kit.

3.3 Connect the Pressure Switch/Switches to the Vehicle Harness


##### **All models except E30**

Reconnect the old pressure switch(es) to the vehicle harness. **Proceed with step 3.4.**

##### **Only E30 models with separate high and low pressure switch**


Refer to the illustrations below.

Cut off  
connector (1)  
from the vehicle  
harness.





S64 96 U08

Splice the wire ends together, solder the connection and insulate it with shrink-wrap tubing (1).




S64 96 U09

Cut off connector (2) from the vehicle harness.



Strip the isolation from the wire ends and install a new black 2-pin connector (1), repair set D, P/N 1 378 400. Splice the wire ends of the new connector together with the wire ends from the harness, solder the connections and insulate it with shrink-wrap tubing (2).

Connect the plug of the new pressure switch to the new connector on the vehicle harness.



### 3.4 Install the service port quick-disconnect adapters.

The larger, red-capped adapter is for the high side line, which runs from the condenser to the evaporator. The line with the sight glass is the high side line.

#### **Only E30 models**

The high side service port is located on the high side pipe.

#### **All models except E30**

The high side service port is located right on top of the receiver dryer.

The smaller, blue-capped adapter is for the low side line, which runs from the evaporator to the compressor inlet.

**Do not overtighten the adapters on the line fittings. The adapters contain O-ring seals and will seat fully with minimum torque. The pipe fitting joints are relatively fragile and will shear if overtightened. A torque of 10-12 Nm should be applied.**

3.5 Connect an R-134a vacuum pump to the vehicle and maintain a vacuum close to 30 inches for a minimum of 40 minutes. This extended vacuum purge will ensure that any remaining R-12 or moisture trapped in the system is boiled away before charging with R-134a. After the vacuum cycle completes, a vacuum decay test should be performed on the sealed system to detect any leaks caused by improperly seated O-rings. Close off all manifold valves and monitor the pressure gauges for a loss of vacuum. Vacuum should not decrease over several minutes.

### 4. Charging A/C System with Lubricant and R-134a Refrigerant

#### 4.1 Charge the system with compressor lubricant

##### **With compressor replacement**

No lubricant has to be charged into the system. The R-134a replacement compressor already contains the appropriate amount of PAG oil.

##### **Without compressor replacement**

Use the established system vacuum to draw in the appropriate amount of PAG lubricant (P/N 82 11 1 468 042) into the A/C system. Refer to the blue charging label included in the retrofit kit for the proper amount of PAG lubricant to use.

4.2 Charge the A/C system with R-134a. The refrigerant flow will push the PAG lubricant out of the service hoses and into the system. Charge with the appropriate amount of refrigerant according to the blue label included in the retrofit kit. Refer to the chart below if the kit contains multiple labels.

| <b>Model</b>                | <b>Fill capacity g (lbs) R-134a</b>   | <b>Old information label R-12 #</b> | <b>New information label R-134a #</b> |
|-----------------------------|---------------------------------------|-------------------------------------|---------------------------------------|
| E30, E28<br>M5              | 900 nīS 25g<br>(1.98 nīS<br>0.05lbs)  | 1 381 958 1 380<br>981              | 8 363 254.9                           |
| E24, E36<br>E28 M10,<br>M20 | 1000 nīS 25g<br>(2.20 nīS<br>0.05lbs) | 1 380 982 2 122<br>023              | 8 363 258.9                           |
| E23, E28<br>M30             | 1100 nīS 25g<br>(2.43 nīS<br>0.05lbs) | 1 380 983                           | 8 363 256.9                           |

#### 5. Checking A/C System for Leaks

Check for leaks with an electronic R-134a leak detector, especially at connections that were opened for the retrofit. Refer to S.I. 04 26 92 (3644) for an approved R-134a leak detector.

#### 6. Verify the A/C System Works Properly.

7. Locate and peel off the original engine-compartment A/C information label. Make certain this area is clean, and attach the new appropriate blue A/C information label from the retrofit kit. If necessary, refer to the chart above to determine the proper label. Both English and German language labels are provided in the kit. The English version of the label should be installed. Record the date and the name of the dealership/service organization that performed the retrofit on the label with a permanent marker.

## **Parts Information:**

|                                       |                          |
|---------------------------------------|--------------------------|
| <b>E23 Retrofit Kit</b>               | 82 31 9 067 400          |
| 64 50 1 365 078                       | O-Ring                   |
| 64 50 8 363 256                       | Label R-134a             |
| 64 11 8 363 259                       | Valve                    |
| 64 11 8 363 260                       | Valve                    |
| 64 53 8 363 554                       | Drying Container         |
| 64 50 8 390 602                       | O-Ring                   |
| 64 50 8 390 603                       | O-Ring                   |
| 01 29 9 788 367                       | Installation Instruction |
| <b>E24 Retrofit Kit (up to 2/86)</b>  | 82 31 9 067 397          |
| 64 50 8 363 255                       | Label R-134a             |
| 64 50 8 363 258                       | Label R-134a             |
| 64 11 8 363 259                       | Valve                    |
| 64 11 8 363 260                       | Valve                    |
| 64 53 8 363 555                       | Drying Container         |
| 64 50 8 390 601                       | O-Ring                   |
| 64 50 8 390 602                       | O-Ring                   |
| 01 29 9 788 367                       | Installation Instruction |
| <b>E 24 Retrofit Kit (as of 2/86)</b> | 82 31 9 067 398          |
| 64 50 8 363 255                       | Label R-134a             |
| 64 50 8 363 258                       | Label R-134a             |
| 64 11 8 363 259                       | Valve                    |
| 64 11 8 363 260                       | Valve                    |
| 64 53 8 363 556                       | Drying Container         |
| 64 50 8 390 601                       | O-Ring                   |
| 64 50 8 390 602                       | O-Ring                   |
| 01 29 9 788 367                       | Installation Instruction |
| <b>E 28 Retrofit Kit</b>              | 82 31 9 067 401          |
| 64 50 8 363 254                       | Label R-134a             |
| 64 50 8 363 256                       | Label R-134a             |
| 64 50 8 363 258                       | Label R-134a             |
| 64 11 8 363 259                       | Valve                    |



|                          |                          |
|--------------------------|--------------------------|
| 64 11 8 363 260          | Valve                    |
| 64 53 8 363 555          | Drying Container         |
| 64 50 8 390 602          | O-Ring                   |
| 64 50 8 390 603          | O-Ring                   |
| 01 29 9 788 367          | Installation Instruction |
| <b>E 30 Retrofit Kit</b> | 82 31 9 067 394          |
| 64 50 8 363 254          | Label R-134a             |
| 64 11 8 363 259          | Valve                    |
| 64 11 8 363 260          | Valve                    |
| 64 50 8 390 601          | O-Ring                   |
| 64 50 8 390 602          | O-Ring                   |
| 64 53 8 390 971          | Pressure Switch          |
| 64 53 8 391 025          | Drying Container         |
| 01 29 9 788 367          | Installation Instruction |
| A/C Compressor           | 64 52 8 363 550          |
| Adapter Wire             | 64 52 1 386 224          |
| PAG lubricant            | 82 11 1 468 042          |

**Warranty  
Information:**

The retrofit of an R-12 system to R-134a is not covered under warranty.